Business Name	Inspection Date	Violation	PDC
RMD HOSPITALITY LLC DBA RAMADA INN	3/10/2020	Lifesaving equipment	Observation: A ring buoy was available but no rope attached. A ring buoy or rescue tube with a minimum outside diameter of twenty (20) inches, to which there must be attached a length of one-quarter (¼) inch rope not less that one and one half (1½) times the maximum width of the pool or swimming area. Emergency telephone was not operable.
RMD HOSPITALITY LLC DBA RAMADA INN	3/10/2020	Pool enclosures	Observation The entry door from the lobby was not secured as a key-card was jammed in the locking mechanism making the pool accessible. The est door closest to the mechanical room for the pool was not closed at the time of inspection and lock was not functioning; the door is not able to close the entire way to allow mechanism to lock.
RMD HOSPITALITY LLC DBA RAMADA INN	3/10/2020	Chlorine/Bromine Levels	Observation Chlorine tested .6 free and .2 combined
RMD HOSPITALITY LLC DBA RAMADA INN	3/10/2020	pH	Observation pH tested above 8
RMD HOSPITALITY LLC DBA RAMADA INN	7/31/2020	Pool enclosures	Observation Not corrected.
RMD HOSPITALITY LLC DBA RAMADA INN	7/31/2020	Lifesaving equipment	Observation Not corrected
RMD HOSPITALITY LLC DBA RAMADA INN	7/31/2020	Chlorine/Bromine Levels	Observation Not Corrected
RMD HOSPITALITY LLC DBA RAMADA INN	7/31/2020	pH	Observation Not corrected
SUNNY MEADOW POOL	2/27/2020	Chlorine/Bromine Levels	Observation Chlorine level .6 Operator corrected during inspection.
SUNNY MEADOW POOL	2/27/2020	Combined Chlorine	Observation Combined chlorine 0. Operator corrected during the inspection.
HOLIDAY INN HOTEL (SPA)	8/6/2020	Chlorine/Bromine Levels	Observation Free Chlorine too low 1.4
HOLIDAY INN HOTEL (SPA)	8/6/2020	Alkalinity	Observation total alkalinity too low 30 ppm
HOLIDAY INN HOTEL (POOL)	8/6/2020	Chlorine/Bromine Levels	Observation Free chlorine too low, closed until disinfectant level above 1; tested .4